



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260629173717
Test Time: 2026-06-29 17:37:17
Technician: --

2010 Mazda Vehicle Diagnostic Report

Vehicle Information

2010/Mazda/MX-5
VIN: JM1NC2JF4E0235584
Path: Manual selection > North America > MX-5 > 2.0L > LF > 2010 > Not equipped > Automatic > No > All Others > Diagnosis > Auto scan >
Odometer Reading: --
License Plate: --
Sub Model: 2.0L/LF

Customer Information

Name: --
Tel: --

Device Information

Scanner: MaxiCheck MX900
Version: V3.31
Serial Number: DR8GRCV02152

☒ Cancel All	21 items selected	Name	Value	Range	Unit
☒	Accelerator Pedal Position		16.07	[0...100]	%
☒	Accelerator pedal position sensor 1 (%)		39.21	[0...100]	%
☒	Accelerator pedal position sensor 1 (V)		1.96	[0...5]	V
☒	Accelerator pedal position sensor 2 (%)		28.23	[0...100]	%
☒	Accelerator pedal position sensor 2 (V)		1.4	[0...5]	V

Time:03:14/16:48

Frame:430/1940